



The State of Utah

Department of  
Natural ResourcesDivision of  
Oil, Gas & MiningROBERT L. MORGAN  
*Executive Director*LOWELL P. BRAXTON  
*Division Director*OLENE S. WALKER  
*Governor*GAYLE F. McKEACHNIE  
*Lieutenant Governor*

## Representatives Present During the Inspection:

OGM	Karl Houskeeper	Environmental Scientist III
Company	Rusty Netz	Environmental Coordinator

**Inspection Report**

Permit Number:	C0070035
Inspection Type:	PARTIAL
Inspection Date:	Monday, June 14, 2004
Start Date/Time:	6/14/2004 10:00:00 AM
End Date/Time:	6/14/2004 12:00:00 PM
Last Inspection:	Wednesday, May 19, 2004

Inspector: Karl Houskeeper, Environmental Scientist IIIWeather: Clear, Temp 90 Deg FInspectionID Report Number: 300Accepted by: pgrubaug  
7/13/2004Permittee: **SUNNYSIDE COGENERATION ASSOCIATES**Operator: **SUNNYSIDE COGENERATION ASSOCIATES**Site: **SUNNYSIDE REFUSE & SLURRY**Address: **PO BOX 159, SUNNYSIDE UT 84539**County: **CARBON**Permit Type: **PERMANENT COAL PROGRAM**Permit Status: **ACTIVE**

## Current Acreages

310.00	Total Permitted
202.00	Total Disturbed
	Phase I
	Phase II
	Phase III

## Mineral Ownership

- ☐ Federal  
☐ State  
☐ County  
☒ Fee  
☐ Other

## Types of Operations

- ☐ Underground  
☐ Surface  
☐ Loadout  
☐ Processing  
☒ Reprocessing

## Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

There are no pending compliance actions. The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. The permittee is complying with this stipulation.

Inspector's Signature

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Date

Monday, June 14, 2004

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801  
 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 [www.ogm.utah.gov](http://www.ogm.utah.gov)

**Utah!**  
 Where ideas connect™

Permit Number: C0070035  
 Inspection Type: PARTIAL  
 Inspection Date: Monday, June 14, 2004

## Inspection Continuation Sheet

Page 2 of 3

### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Permit Number: C0070035  
Inspection Type: PARTIAL  
Inspection Date: Monday, June 14, 2004

**Inspection Continuation Sheet**

**Page 3 of 3**

**2. Signs and Markers**

The mine ID sign is located adjacent to the tipple. The MSHA Refuse and Impoundment signs were also checked during the inspection.

**4.d Hydrologic Balance: Water Monitoring**

First quarter 2004 water monitoring information has been submitted into the EDI website and uploaded. Baseline parameters were used to analyze the samples. Water monitoring is current.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

The refuse pile appeared stable with no visible hazards.